

It	Number	Location	Status	Done	Comment
					GROUND FLOOR
1	WG01	Front bay	Made. In store	☐	Double hung, double glazed
2	WG02	Front bay	Made. In store	☐	Ditto with mullion
3	WG03	Front bay	Made. In store	☐	Ditto with mullion
4	WG04	Front bay	Made. In store	☐	Double hung, double glazed
5	WG05	Porch	Pending	☐	Leaded lights, distorted by collapse
6	WG06	Porch	Pending	☐	"
7	WG07	Porch	Pending	☐	"
8	WG08	Porch	Pending	☐	"
9	WG09	Guest bedroom	Overhaul	☐	Remove existing secondary glazing. Add new shutters or secondary s/g glazing + insulate jambs..
10	WG10	GF en suite	replaced	☐	Adapt opening and fit former WF08
11	WG11	GF en suite	To be made	☐	Double hung, double glazed new sash/w
12	WG12	GF en suite	omitted	☐	brick up opening and adapt sill
13	WG12	GF stair lobby	newly made	☐	reassign window number to newly made double glazed deadlight to site size as drawn
14	WG13	Store		☐	
15	WG14	Glass house	Pending	☐	
16	WG15	Glass house	Pending	☐	
17	WG16	Glass house	Pending	☐	
18	WG17	Glass house	Pending	☐	
19	WG18	Glass house	Pending	☐	
20	WG19	Glass house	Pending	☐	
21	WG20	Glass house	Pending	☐	
22	WG21	Sitting room	Made, fitted	☒	Double hung, double glazed new sash/w
23	WG22	Solarium	Pending	☐	
24	WG23	Solarium	Pending	☐	
25	WG24	Solarium	Pending	☐	
26	WG25	Solarium	Pending	☐	
27	WG26	Solarium	Pending	☐	
28	WG27	Solarium	Pending	☐	
29	WG28	Solarium	Pending	☐	
30	WG29	Dining room	Made, fitted	☒	Double hung, double glazed new sash/w
31	WG30	Utility room	overhaul and move to location of WF08	☐	Block opening with OSB. Salvage sashes (?) and make new case or make new.
					FIRST FLOOR
32	WF01	Front bay	Bedroom.FF03	☐	Double hung, double glazed new sash/w
33	WF02	Front bay	Bedroom.FF03	☐	Double hung, double glazed new sash/w
34	WF03	Front bay	Bedroom.FF03	☐	Double hung, double glazed new sash/w
35	WF04	Front bay	Bedroom.FF03	☐	Double hung, double glazed new sash/w
36	WF05 a	Bathroom		☐	New safe lintel required
37	WF05b	Bathroom		☐	Remove existing secondary glazing. Add new shutters or secondary s/g glazing + insulate jambs..
38	WF06 a	NE bedroom	FF04	☐	Remove existing secondary glazing. Add new shutters or secondary s/g glazing + insulate jambs..

Colour key		
	New window	(18)
	Existing overhauled	(7)
	Deferred	(18)
	Delete	(4)

It	Number	Location	Status	Done	Comment
					GROUND FLOOR
39	WF06b	NE bedroom	FF04	☐	Remove existing secondary glazing. Add new shutters or secondary s/g glazing + insulate jambs..
40	WF07	FF en suite	FF05	☐	Stained glass vss window much rot
41	WF08 (for WG10)	FF en suite		☐	Overhaul or new copy of WG30 fitted to east end of opening, bricked to size.
42	WF09	FF en suite		☐	Double hung, double glazed new sash/w
43	WF10	NW bedroom		☒	
44	WF11	NW bedroom		☒	
45	WF12	SW bedroom		☒	
46	WF13	SW bedroom		☒	
47	WF14	Staircase window		☐	Remove existing secondary glazing. Fix top sash.
				☐	